

SECRET

25X1

IDEA-0916-69  
Copy 6 of 7

6 November 1969

MEMORANDUM FOR: Deputy for Operations, OSA

25X1

SUBJECT : [REDACTED] Station Activity Report  
September 1969

1. Reference PART I A. (5) and D.1. (a) on the LOX low-pressure lights has been reviewed.

2. Life Support agrees that most likely there was insufficient buildup time in this particular instance. However, historically, the 1-to-24 hours filling period prior to a given flight has been successful in both Air Force LOX Systems as well as with the experience over the past year [REDACTED] (See attachment [REDACTED])

25X1

25X1

3. In the absence of any additional episodes of this dyscrasia, it is felt that the existing policy should remain as the SOP.

25X1

[REDACTED]  
AMS/OSA

Attachment  
As stated above

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

[REDACTED]  
SECRET

25X1

SECRET


25X1

IDEA-0916-69

Page 2

25X1

AMS/OSA



Distribution:

- 1 - Addee
- 2 - C/Idea/O/OSA
- 3 - C/SAS/O/OSA
- 4 - D/M/OSA
- 5 - AMS/OSA
- 6 - " Chrono
- 7 - RB/OSA

SECRET

25X1